

SAFETY ALERT

Scalding Accident to Plant Operator



PLEASE READ THIS AND TAKE NOTE OF WHAT HAS HAPPENED

Injured Person was operating his 18Ton excavator when the machine started to overheat.

Injured Person stopped the machine and proceeded to inspect the engine bay.

Injured Person walked to the compartments on the side of the machine and removed two water bottles with spare water for topping up the radiator.

Injured Person then walked on the top of the machine, and unlocked, using the ignition key, the radiator cap cover.

Injured Person started to undo the radiator cap.

The cap was under pressure, and blew off, throwing hot liquid (of exact type remains to be identified) burning Injured Persons face and body.



**IF THE DISPLAY ON YOUR MACHINE DISPLAYS AN
OVERHEATING WARNING:**

**THEN STOP THE MACHINE, ALLOW IT TO COOL
BEFORE FURTHER INVESTIGATION AND THEN
MAKE THE SITE MANAGER AWARE OF THE
PROBLEM.**

FOLLOW THE MANUFACTURERS INSTRUCTIONS.

PLEASE LETS NOT HAVE A REPEAT INCIDENT.